



IMPORTANT SAFETY RECALL

ECHO PB-265L BACKPACK BLOWER Produced from August 2011 through November 2011

The fuel line assembled to the carburetor may have pin holes at the end attached to the carburetor fuel inlet fitting, which could allow leakage of gasoline and fuel vapor, presenting a potential fire hazard.



PB-265L Blower



Serial Number Location

Model	Description	Starting S/N	Ending S/N
PB-265L	Backpack Blower	P09312135519	P09312150152
PB-265L	Backpack Blower	P07811020732	P07811022309

If your ECHO PB-265L Backpack Blower is within the recall serial number range, **you should discontinue use of this product immediately** and contact your local authorized ECHO service dealer for free repair of your blower.

For further information, visit www.echo-usa.com or call ECHO's toll free number between 8:30 a.m. and 4:30 p.m. (central time) Monday – Friday at 800-432-3246 to speak to a company representative.

February 17, 2012